Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* AD 2018-0137R1 - AIRBUS: Nacelles / Pylons - Pylon Aft Fixed Fairings - Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0137R1

\* **AD** 2018-0265R1 - BRP-ROTAX GmbH & Co KG: Engine – Exhaust Valve – Replacement

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0265R1

\* PAD 19-002 - AIRBUS HELICOPTERS DEUTSCHLAND: Airworthiness Limitation Section – TT-Straps – Storage Life Limit

TO see the details OF this Publication, please click OR copy the following: URL: <a href="http://ad.easa.europa.eu/ad/19-002">http://ad.easa.europa.eu/ad/19-002</a>

\* **PAD** 19-003 - AIRBUS: Flight Controls – Flight Control Primary Computer – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <a href="http://ad.easa.europa.eu/ad/19-003">http://ad.easa.europa.eu/ad/19-003</a>

\* **PAD** 19-004 - SOLO KLEINMOTOREN GmbH: Engine – Propeller Reduction Gear Excentric Axle Bearings – Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <a href="http://ad.easa.europa.eu/ad/19-004">http://ad.easa.europa.eu/ad/19-004</a>