The following Documents have been published or updated by EASA and may be of interest to you:

* AD 2019-0211 - CEAPR: Engine – Thermostatic Oil Cooler Bypass Valve – Inspection / Installation

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0211

* PAD 19-161 - ATR: Flight Controls – Bonding Braid Screw and Pitch Tab Control Rod – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/19-161