Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** CF-2016-32R3 - BOMBARDIER: Fuel - Engine and Auxiliary Power Unit Electrical Fuel Pump Cartridge/Canister Fuel Leakage

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CF-2016-32R3

* **AD** CF-2018-26R1 - BOMBARDIER: Landing Gear â€" Main Landing Gear Side Stay Actuators Contain Non-Conforming Split Ball Bearing

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CF-2018-26R1

* PAD 19-086 - FOKKER SERVICES: Stabilizers â€" Horizontal Stabilizer Rear Spar Attachment Angles â€" Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-086

* PAD 19-087 - FOKKER SERVICES: Fuselage â€" Bottom Skin â€" Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-087

* PAD 19-089 - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-089

* PAD 19-091 - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-091

* PAD 19-090 - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-090

* **PAD** 19-088 - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/19-088