

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** CF-2019-12 - BOMBARDIER: Auto Flight System – Airplane Flight Manual Limitations and Emergency Procedures – Velocity Decay during Low Level Altitudes Capture in One Engine Inoperative Conditions

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2019-12>

---

\* **PAD** 19-059 - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – High Pressure Turbine Blades – Inspection / De-Pairing Limitation

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/19-059>