

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2019-0220R1** - AIRBUS: Fuselage – Rear Cone Frame Feet 102/103 – Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0220R1>

* **PAD 19-213** - AIRBUS: Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 2 – Damage Tolerant Airworthiness Limitation Items – Implementation

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-213>

* **AD 2019-0305** - AIRBUS HELICOPTERS DEUTSCHLAND: Wiring Harness – Cabin Wiring Harness – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0305>

* **AD US-2019-22-01** - BOEING: Wings - Side of Body Rib - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2019-22-01>
