

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2019-0064R1** - AIRBUS HELICOPTERS: Doors – Cabin Sliding Plug Doors / Emergency Jettisoning System – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0064R1>

* **AD 2019-0304R1** - AIRBUS: Engine – Operational Restrictions

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0304R1>

* **PAD 19-217** - AIRBUS: Equipment / Furnishings – Emergency Locator Transmitter – Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-217>

* **AD 2019-0311** - LEONARDO S.p.A. HELICOPTERS: Equipment / Furnishings, Emergency Flotation System – Inflation Hoses – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0311>

* **PAD 19-218** - AIRBUS HELICOPTERS: Fuselage – Lower Fuselage Fuel Tank Structure and Equipment Electrical Connectors – Rework / Relocation

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-218>