

The following Documents have been published or updated by EASA and may be of interest to you:

* **PAD 19-219** - AIRBUS: Pneumatic – Engine Bleed Air Supply System High Pressure Valves – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-219>

* **PAD 19-220** - AIRBUS: Doors – Passenger Door Triple Reed Contact Switches – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-220>

* **PAD 19-221** - AIRBUS: Doors – Auxiliary Wing Landing Gear Doors – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-221>

* **AD 2019-0313** - AIRBUS HELICOPTERS DEUTSCHLAND: Rotors Flight Control – Tail Rotor Actuator – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0313>

* **AD 2019-0312** - AIRBUS: Aircraft Flight Manual – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0312>