The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2018-0142R1 - AIRBUS HELICOPTERS: Equipment & Furnishings / Ice and Rain Protection / Fuselage — Dual Hoist Removable Parts or De-icing System — Removal

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2018-0142R1

* **AD** 2019-0114 - AIRBUS: SUPERSEDED BY EASA AD 2019-0297

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0114

* **AD** 2019-0273R1 - DASSAULT AVIATION: Airplane Flight Manual – Section Normal Procedures – Amendment

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0273R1

* **AD** 2019-0296 - SAFRAN HELICOPTER ENGINES: Engine Fuel & Control – Fuel Filter Pre-Blockage Pressure Switch – Replacement

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0296

^{*} AD 2019-0297 - AIRBUS: Wings – Lower Skin Covers at Rib Bays – Inspection