

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** F-1995-063R5 - AIRBUS: SUPERSEDED BY EASA AD 2019-0044

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/F-1995-063R5>

* **AD** F-1998-040R1 - AIRBUS: SUPERSEDED BY EASA AD 2019-0044

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/F-1998-040R1>

* **AD** 2019-0044 - AIRBUS: Wings – Centre Section Frame 40 Forward Fitting Radius at Tension Bolt Junction – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0044>

* **PAD** 19-034 - AIRBUS: Stabilizers – Elevators – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/19-034>