

The following Documents have been published or updated by EASA and may be of interest to you:

\* **PAD 19-148** - PILATUS AIRCRAFT LTD: Flight Controls – Flap Drive System / Flap Fairings and Front Inboard Tension Rods – Inspection / Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-148>

---

\* **PAD 19-147** - LEONARDO S.p.A. HELICOPTERS: Hydraulic Power – Hydraulic Pumps – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-147>

---

\* **AD 2019-0186** - GUIMBAL, HELICOPTERS: Rotors Flight Control – Main Rotor / Non-Rotating Scissor Link – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0186>

---

\* **PAD 19-149** - PILATUS AIRCRAFT LTD: Fuel – Saddle Clamps / Motive-Flow Fuel Pipes – Replacement / Alignment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-149>

---

\* **PAD 19-150** - FOKKER SERVICES: Landing Gear – Main Landing Gear / Piston – Inspection / Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-150>