

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2018-0249R1** - AIRBUS: [Correction] Wings – Centre Wing Box Fastener Holes at Frame 40 Vertical Web – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2018-0249R1>

* **AD 2019-0187** - GUIMBAL, HELICOPTERES: [Correction] Powerplant – Engine Cooling Fan – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0187>

* **PAD 19-135R1** - DIAMOND AIRCRAFT INDUSTRIES: Fuel – Fuel Tank Connection Hoses – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-135R1>

* **PAD 19-152** - AIRBUS: Exhaust – Thrust Reverser Cascades and Aft Frame Attachment – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-152>