The following Documents have been published or updated by EASA and may be of interest to you:

\* AD 2018-0044-CN - SAFRAN HELICOPTER ENGINES: CANCELLED: Engine – Power Turbine Wheels – Replacement

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/2018-0044-CN</u>

\* AD 2019-0036 - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2019-0174

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/2019-0036</u>

\* AD 2019-0173 - AIRBUS: Fuselage – Cockpit Lateral Window Frames – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/2019-0173</u>

\* AD 2019-0172 - AIRBUS HELICOPTERS: Main Rotor – Hub Assembly Lock Washer – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/2019-0172</u>

\* **AD** 2019-0174 - LEONARDO S.p.A. HELICOPTERS: Main Rotor Drive – Main Gearbox Bearing Lock-Nut – Replacement

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/2019-0174