

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2019-0272R1** - AIRBUS HELICOPTERS: Tail Rotor – Tail Rotor Hub Body – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0272R1>
