

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2019-0181R1** - AIRBUS: Fuselage – Forward and Aft Cargo Door Latch Fitting External Lugs – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0181R1>

* **AD 2019-0278** - ATR: Electronic Common Installation – Engine Nacelle Electrical Wiring – Modification; Hydraulic Power – Underwing Box Hydraulic Pipe – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0278>

* **AD 2019-0267R1** - AIRBUS HELICOPTERS: Tail Rotor – Double Bearing – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0267R1>

* **PAD 19-203** - WSK PZL - SWIDNIK S.A.: Main Rotor – Lower and Upper Torque Scissors – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-203>