

**Transport Canada / Transports Canada
Civil Aviation / Aviation Civile**

**** Le texte français suit l'anglais. ****

The following has recently been posted to the [Transport Canada AD website](#):

Number: CF-2019-33

Subject: ATA - 32 LANDING GEAR – TRAILING ARM ASSEMBLY AXLE BORE CORROSION

Applicability: Bombardier Inc. model BD-700-1A10 and BD-700-1A11 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2019-33-E.PDF>

Number: CF-2017-05R2

Subject: ATA 28 - FUEL SYSTEM – MOTIVE FLOW LINE FOULING AND MOTIVE FLOW LINE AND PRESSURE RELIEF LINE BROKEN P-CLAMPS AND VENT LINE TEFLON SLEEVE INSTALLATION

Applicability: Bombardier Inc. model DHC-8-400, -401 and -402 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2017-05R2-E.PDF>

Number: CF-2019-34

Subject: ATA 65 - TAIL ROTOR DRIVE – FAILURE OF TAIL ROTOR DRIVE SHAFT COUPLING BOLTED CONNECTIONS

Applicability: Bell Helicopter Textron Canada Limited (BHTCL) model 206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3 and 206L-4 helicopters

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2019-34-E.PDF>