

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** CF-2017-05R2 - DE HAVILLAND AIRCRAFT OF CANADA LTD.: Fuel System – Motive Flow Line Fouling, Motive Flow Line and Pressure Relief Line Broken P-Clamps, and Vent Line Teflon™ Sleeve Installation

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/CF-2017-05R2>

---

\* **AD** US-2017-11-09 - LEARJET, INC.: SUPERSEDED BY FAA AD 2019-17-01

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2017-11-09>

---

\* **AD** US-2019-17-01 - LEARJET, INC.: Fuselage - Upper Fuselage Skin - Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2019-17-01>