

The following Documents have been published or updated by EASA and may be of interest to you:

\* **PAD 19-085R1** - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – Intermediate Pressure Compressor Blades / Shaft – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-085R1>

---

\* **PAD 19-168** - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – Intermediate Pressure Compressor Blades / Shafts – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-168>

---

\* **PAD 19-166** - AIRBUS HELICOPTERS: Doors – Cargo Door Locking Mechanism – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-166>

---

\* **PAD 19-167** - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – Intermediate Pressure Compressor Blades / Shaft – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-167>

---

\* **AD CF-2019-31** - AIRBUS CANADA LP: Ice and Rain Protection – Insufficient Engine Core Ventilation Resulting in Higher Engine Core Temperatures

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/CF-2019-31>