

The following Documents have been published or updated by EASA and may be of interest to you:

* **PAD 19-169** - AIRBUS: Fuselage – Lateral Window Frame Upper Fastener Holes – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-169>