

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2019-0135** - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: SUPERSEDED BY EASA AD 2019-0261

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0135>

---

\* **AD 2019-0261** - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – Intermediate Pressure Turbine Blades – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0261>

---

\* **PAD 19-190R1** - AIRBUS: Flight Controls – Stop Rudder Input Warning Device – Installation / Activation

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-190R1>

---

\* **AD 2019-0258** - AIRBUS HELICOPTERS DEUTSCHLAND: Tail Rotor Drive – Titanium Bolts – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0258>

---

### **IMPORTANT NOTICE**

The draft Agenda is now available [here](#).

The 7th EASA Airworthiness Directives (AD) Workshop will be held on **25-26 November 2019** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information and online registration are available [here](#).

EASA Safety Information Section