The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** CF-2016-13R1 - BELL HELICOPTER TEXTRON CANADA (BHTC): Main Rotor Drive — Loss of Lubrication to the Freewheel Assembly

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/CF-2016-13R1">https://ad.easa.europa.eu/ad/CF-2016-13R1</a>

\* AD US-2019-15-07 - BOEING: [Correction] Fuselage - Fuselage Lower Lobe Frames - Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/US-2019-15-07">https://ad.easa.europa.eu/ad/US-2019-15-07</a>

## **IMPORTANT NOTICE**

The 7th EASA Airworthiness Directives (AD) Workshop will be held on **25-26 November 2019** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information and online registration are available <u>here</u>.

**EASA Safety Information Section**