

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2019-0240** - PILATUS AIRCRAFT LTD: Fuel – Saddle Clamps / Motive-Flow Fuel Pipes – Replacement / Alignment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0240>

---

\* **PAD 19-177** - 328 SUPPORT SERVICES: Time Limits / Maintenance Checks – Certification Maintenance Requirements / Airworthiness Limitations Section – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-177>

---

\* **PAD 19-179-CN** - 328 SUPPORT SERVICES: CANCELLED: Flight Controls – Tab-to-Actuator Linkage – Inspection / Fuel – Fuel Airworthiness Limitations – Implementation [Fuel Tank Safety]

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-179-CN>

---

\* **AD CF-2019-32** - PRATT & WHITNEY CANADA: Engine – High Pressure Turbine Rear Cover Life Limitation Reduction

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/CF-2019-32>

---

\* **PAD 19-178** - 328 SUPPORT SERVICES: Time Limits / Maintenance Checks – Certification Maintenance Requirements / Airworthiness Limitations Section – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-178>

---

\* **PAD 19-180** - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: Engine – Intermediate Pressure Turbine Blades – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/19-180>

---