

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** US-2016-18-01 - BOEING: SUPERSEDED BY FAA AD 2019-01-03

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2016-18-01>

* **EAD** 2019-0055-E - BRP-ROTAX GmbH & Co KG: [Correction] Engine fuel and Control – Fuel Pump Assembly – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0055-E>

* **AD** US-2019-01-06 - BOEING: Fuselage - Frame Web and Doubler - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2019-01-06>

* **AD** US-2019-01-03 - BOEING: Landing Gear - Trunnion Pin Assemblies - Inspection / Lubrication / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2019-01-03>