

## EASA Certification Information

**No.:** 2019-26  
**Issued:** 09 July 2019

**Subject:** Notice of intent to revoke European Technical Standard Order Authorisations No. EASA.21O.10034034, No. EASA.21O.10034933, No. EASA.21O.766, No. EASA.21O.760 and No. EASA.21O.727 issued to GEMELLI S.p.A. due to non-compliance with Commission Regulation (EU) No. 319/2014 on the fees and charges levied by the European Aviation Safety Agency

**Authorisation No.:**

ETSOA No.	Description	Part Number(s)	Date of last issue	DDP Reference.
EASA.21O.10034034	GEM-05 Cabin Operator Communication Unit	GEM-05-COCU-( )-( )-( )	02/03/2011	DDP- GEM-05-COCU-( )-( )-( )
EASA.21O.10034933	GEM-06-ICDU	GEM-06-ICDU-( )-( )-( )	13/05/2011	DDP- GEM-06-ICDU-( )-( )-( )
EASA.21O.766	Internal Communication Distribution Unit	GEM-10-RIB-( )-( )-( )	28/06/2011	DDP- GEM-10-RIB-( )-( )-( )
EASA.21O.760	GEM-10-CCCU-( )-( )-( )	GEM-10-CCCU-( )-( )-( )	27/04/2012	DDP- GEM-10-CCCU-( )-( )-( )
EASA.21O.727	Headset HG-222	HG-222-( )-( )-( )	20/07/2010	HG-222-( )-( )-( )

**Issued by:** European Union Aviation Safety Agency

**ETSOA Holder:** GEMELLI, S.p.A.  
 Via Piave, 18  
 20010  
 USA

**Background:** GEMELLI S.p.A. is the holder of European Technical Standard Order Authorisations No. EASA.21O.10034034 for Part Number GEM-05-COCU-( )-( )-( ), No. EASA.21O.10034933 for Part Number GEM-06-ICDU-( )-( )-( ), No. EASA.21O.766 for Part Number GEM-10-RIB-( )-( )-( ), No. EASA.21O.760 for Part Number GEM-10-CCCU-( )-( )-( ) and No. EASA.21O.727 for Part Number HG-222-( )-( )-( ).

According to Article 7 (2) in conjunction with Table 6 of Part 1 of the Annex to Commission Regulation (EU) No. 319/2014<sup>1</sup> holders of European Technical Standard Order Authorisations are required to pay an annual fee related to the certification tasks

<sup>1</sup> [Commission Regulation \(EU\) No 319/2014 of 27 March 2014 on the fees and charges levied by the European Aviation Safety Agency, and repealing Regulation \(EC\) No 593/2007 \(OJ L 93, 28.3.2014, p. 58\)](#)



carried out by the Agency for the purpose of maintaining the European Technical Standard Order Authorisation.

Despite several reminders, GEMELLI S.p.A. fails to fulfil the payment obligations imposed by Commission Regulation (EU) No. 319/2014.

Due to this persistent non-compliance, EASA intends to revoke European Technical Standard Authorisations No. EASA.21O.10034034, No. EASA.21O.10034933, No. EASA.21O.766, No. EASA.21O.760 and No. EASA.21O.727 in accordance with Article 10 (1) of Commission Regulation (EU) No. 319/2014.

EASA hereby asks you to communicate this notice to any natural or legal person to whom this revocation could be of direct and individual concern as well as to other possible interested persons. When doing so, EASA also asks you to inform them about the possibility of commenting on the above **until 8<sup>th</sup> August 2019**.

A list of the direct and individual concerned and other possible interested persons should be sent to EASA.

After satisfactory evaluation of the comments received, EASA may take the decision to revoke the European Technical Standard Order Authorisations No. EASA.21O.10034034, No. EASA.21O.10034933, No. EASA.21O.766, No. EASA.21O.760 and No. EASA.21O.727 in accordance with the applicable administrative procedures established by EASA.

**Contact:**

Any request, query or comment should be sent, **no later than 8<sup>th</sup> August 2019**, to:

European Union Aviation Safety Agency  
Attn. Mrs. Caroline RUGA  
Postfach 10 12 53  
D – 50452 Köln  
Deutschland  
E-Mail: [caroline.ruga@easa.europa.eu](mailto:caroline.ruga@easa.europa.eu)

