

**Occurrence Communication:** Oc00047-2019**Date:** 22/Jan/2019

Page 1 of 1

**Type: Major Event**

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-135 ER	<b>Serial Number:</b> 145243
<b>Marks:</b> V5-ANF	<b>Operator:</b> AIR NAMIBIA	<b>Occurrence Date:</b> 17/Jan/2019
<b>Ata:</b> 72	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> HOSEA KUTAKO INTL - WINDHOEK - NAMIBIA		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of uncommanded engine 1 IFSD  
The flight crew reported an uncommanded engine 1 IFSD just after the takeoff. They then returned to the departure airport where an uneventful single engine landing was performed.

Maintenance personnel found metal particles in the engine 1 tailpipe during inspection. The engine 1 will be removed and replaced.