

**EMBRAER S.A.**

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901  
Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

**Occurrence Communication:** Oc00053-2019      **Date:** 28/Jan/2019

Page 1 of 1

**Type: Serious Incident**

<b>Aircraft:</b> EMB-500	<b>Model:</b> EMB-500	<b>Serial Number:</b> 5000048
<b>Marks:</b> PR-CSW	<b>Operator:</b> CONSTRUTORA	<b>Occurrence Date:</b> 25/Jan/2019
<b>Ata:</b> 00	<b>Time:</b> 7:00 PM	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> Sao Joao del Rei Airport, Minas Gerais, Brazil		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of runway excursion during landing  
It was reported that the aircraft experienced a runway overrun during landing. Preliminary information indicates that the runway was wet at the time of occurrence.

**ADDITIONAL INFORMATION:**

This event is under investigation by SERIPA 3, with assistance from Embraer.