

## EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00099-2019 Date: 20/Mar/2019

Page 1 of 1

## **Type: Major Event**

Aircraft:	Model:	Serial Number:
EMB-145	EMB-135 LR	145506
Marks: N807AE	Operator: ENVOY	Occurence Date: 18/Mar/2019
<b>Ata:</b> 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: X None Light:	0 Serious: 0	Fatal: <sup>0</sup>

## **Occurence Description:**

Report of smoke in the cockpit during flight The flight crew reported smoke in the cockpit during flight.

Maintenance personnel found ACM 1 making an abnormal noise. They then removed and replaced the ACM. Subsequent operational checks were satisfactory.