

## EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00117-2019 Date: 29/Mar/2019

Page 1 of 1

## Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 LR	145547
<b>Marks:</b> N14542	<b>Operator:</b> EXPRESSJET	Occurence Date: 27/Mar/2019
<b>Ata:</b> 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: JACKSONVILLE INTL - JACKSONVILLE - FL - UNITED STATES		
Injuries: X None Light:	0 Serious: 0 F	atal: <sup>0</sup>

## Occurence Description:

## Report of smoke on board

The flight crew reported that shortly after take off, pack #1 overheated and they noticed smoke in the cabin. They then returned to the departure airport.