

**Occurrence Communication:** Oc00128-2019      **Date:** 10/Apr/2019

Page 1 of 1

**Type: Major Event**

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-145 XR	<b>Serial Number:</b> 145953
<b>Marks:</b> N11199	<b>Operator:</b> COMMUTAIR	<b>Occurrence Date:</b> 08/Apr/2019
<b>Ata:</b> 72	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> CINCINNATI/NORTHERN KY INTL - CINCINNATI - KY - UNITED STATES		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of uncommanded engine 2 IFSD during descent  
The flight crew reported an abnormal noise on engine 2 during descent, followed by an uncommanded engine 2 IFSD. An uneventful single engine landing was performed.

Maintenance personnel found metal pieces in the compressor inlet during the engine visual inspection.