

Occurrence Communication: Oc00154-2019 **Date:** 07/May/2019

Page 1 of 1

Type: Other

Aircraft: EMB-145	Model: EMB-135 LR	Serial Number: 145656
Marks: N840AE	Operator: ENVOY	Occurrence Date: 30/Apr/2019
Ata: 28	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of precautionary engine 2 IFSD
The flight crew reported they commanded the engine 2 shutdown during flight in order to save fuel.
They also reported the APU failed to start after the engine 2 shutdown.

The APU was deferred per MEL.