

Occurrence Communication: Oc00155-2019 **Date:** 07/May/2019

Page 1 of 1

Type: Major Event

Aircraft: EMB-145	Model: EMB-145 LR	Serial Number: 145911
Marks: N928AE	Operator: ENVOY	Occurrence Date: 04/May/2019
Ata: 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: LAMBERT-ST LOUIS INTL - ST LOUIS - MO - UNITED STATES		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of smoke in the cockpit.
The flight crew reported smoke in the cockpit while crossing FL230 coming from air vents. Flight attendant reported a loud grinding noise in the area around wing at the same time that the smoke was notice in the cockpit.
Maintenance Personnel found #1 pack ACM(Air Cycle Machine) seized and dual temperature control valve to heat exchanger duct damaged. Both were removed and replaced