

## EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00161-2019 Date: 09/May/2019

Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 LR	145476
<b>Marks:</b> N14905	Operator: EXPRESSJET	Occurence Date: 14/Jul/2018
<b>Ata:</b> 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: LAMBERT-ST LOUIS IN	ITL - ST LOUIS - MO - UNITED S	TATES
Injuries: X None	Light: <sup>0</sup> Serious:	0 <b>Fatal:</b> 0

## **Occurence Description:**

Report of smoke inside cabin and cockpit.

The flight crew reported smoke in the cabin and cockpit, with possible pack failure. No message was displayed. They then decided to divert to a suitable airport.

Maintenance personnel removed and replaced #1 air cycle machine