

Occurrence Communication: Oc00263-2019 **Date:** 01/Jul/2019

Page 1 of 1

Type: Other

Aircraft: EMB-145	Model: EMB-135 LR	Serial Number: 145489
Marks: N805AE	Operator: ENVOY	Occurrence Date: 15/Sep/2018
Ata: 53	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of machined fitting at frame 19-20 stringer 3L found cracked during inspection
MACHINED FITTING AT FR 19-20 STR 3L CRACKED-C/A-REMOVED AND REPLACED MACHINED FITTING
AT FR 19 STR 3L IAW SRM 51-40-02