

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00481-2019 Date: 08/Nov/2019

Page 1 of 1

|--|

Aircraft:	Mo	odel:	Serial Number:
EMB-145	EN	1B-135 KL	145722
Marks:	Op	perator:	Occurence Date:
N850AE	EN	IVOY	24/May/2019
Ata: 21	Tir	ne:	Number of Persons Aboard: Not Available
Aircraft Damages:			
Site: NOT AVAILABLE			
Injuries: X None	Light: 0	Serious: ⁰	Fatal: ⁰

Occurence Description:

Report of smoke in the cockpit and cabin

The flight crew reported smoke in the cockpit and cabin and returned to land.

Maintenance personnel found the left air cycle machine (ACM 1) damaged. They removed and replaced the left ACM. Subsequent operational checks were satisfactory.