

Occurrence Communication: Oc00494-2019 **Date:** 25/Nov/2019

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 LR	Serial Number: 145501
Marks: N48901	Operator: EXPRESSJET	Occurrence Date: 23/Jun/2019
Ata: 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of fumes and vapor or minor smoke in the cabin during flight
The flight crew reported fumes and vapor or minor smoke inside the cabin during flight.

Maintenance personnel removed and replaced the air cycle machine 2 (ACM 2). Subsequent operational checks were satisfactory.