Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* AD 2018-0164R1 - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: [Correction] Engine – High Pressure Turbine Disc Front Cover Plate – Replacement [Life Limitation]

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/2018-0164R1</u>

\* PAD 19-042 - AIRBUS HELICOPTERS: Fuel – Engine Fuel Supply Hoses – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/19-042</u>

\* **PAD** 19-043 - DASSAULT AVIATION: Fire Protection – Fire Extinguisher Percussion Cartridge – Life Limit

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/19-043</u>