

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2017-0022 - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2019-0064

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/2017-0022>

---

\* **AD** 2019-0065 - AIRBUS: Fuselage – Rear Fuselage Cone Diagonal Struts – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/2019-0065>

---

\* **AD** 2019-0064 - AIRBUS HELICOPTERS: Doors – Cabin Sliding Plug Doors /  
Emergency Jettisoning System – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/2019-0064>

---

\* **PAD** 19-047 - AIRBUS: Pneumatic – Bleed Monitoring Computer – Modification /  
Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/19-047>

---