

**Transport Canada / Transports Canada
Civil Aviation / Aviation Civile**

**** Le texte français suit l'anglais. ****

The following has recently been posted to the [Transport Canada AD website](#):

Number: CF-2014-08R1

Subject: **ATA 52 - DOORS – TRANSLATING DOORS LOOSE BOLTS**

Applicability: De Havilland Aircraft of Canada Limited (formerly Bombardier Inc.) model DHC-8-400, -401 and -402 aeroplanes.

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2014-08R1-E.PDF>

Number: CF-2010-30R2

Subject: **ATA 54 - CRACKING OF THE NACELLE ATTACHMENT FITTING(S)**

Applicability: De Havilland Aircraft of Canada Limited (formerly Bombardier Inc.) model DHC-8-400, -401 and -402 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2010-30R2-E.PDF>

Number: CF-2002-39R2

Subject: **ATA 53 - BOMBARDIER CL-600-2B19 - FUSELAGE PRESSURE FLOOR SKIN**

Applicability: Bombardier Inc. model CL-600-2B19 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2002-39R2-E.PDF>

You are receiving this notification as a subscriber to the Transport Canada Civil Aviation e-Bulletin alert service. To unsubscribe, please use the form available on this Web page:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/menu-1152.htm>

For further information on **e-Bulletin**, you may wish to visit:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/managementservices-referencecentre-menu-113.htm> .

You can also contact Transport Canada's Civil Aviation Communications Centre at 1-800-305-2059 or at services@tc.gc.ca for questions regarding this service.

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#) :

Numéro: CF-2014-08R1

Sujet: **ATA 52 - PORTES – BOULONS DESSERRÉS SUR LES PORTES COULISSANTES**

Applicabilité: Les avions de De Havilland Aircraft of Canada Limited (anciennement Bombardier Inc.) modèle DHC-8-400, -401 et -402

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2014-08R1-F.PDF>

Numéro: CF-2010-30R2

Sujet: **ATA 54 - FISSURATION DE FERRURES DE FIXATION DE FUSEAU-MOTEUR**

Applicabilité: Les avions de De Havilland Aircraft of Canada Limited (anciennement Bombardier Inc.) modèle DHC-8-400, 401 et 402

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2010-30R2-F.PDF>

Numéro: CF-2002-39R2

Sujet: **ATA 53 - BOMBARDIER CL-600-2B19 – REVÊTEMENT DE PLANCHER ÉTANCHE DU FUSELAGE**

Applicabilité: Les avions de Bombardier Inc. modèle CL-600-2B19

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2002-39R2-F.PDF>

Vous recevez cet avis électronique à titre d'abonné au service d'alerte par courriel de Transports Canada Aviation civile. Si vous désirez vous désabonner, veuillez utiliser le formulaire disponible à cette page Web : <http://www.tc.gc.ca/fra/aviationcivile/opssvs/menu-1152.htm>

Pour autres informations reliées au bulletin électronique, vous pouvez visiter :

<http://www.tc.gc.ca/fra/aviationcivile/opssvs/servicesdegestion-centredereference-menu-113.htm>.

Vous pouvez contacter le Centre de communications de l'Aviation civile de Transports Canada au 1-800-305-2059 ou services@tc.gc.ca pour toutes questions à l'égard de ce service

#####