Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* SIB 2017-18R1 - Safety Information Bulletin: Airbus Helicopters AS 350 / EC 130 Helicopters - Installation of Crash Resistant Fuel System

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2017-18R1

\* SIB 2019-08 - Safety Information Bulletin: Safran Aerosystems Flight Crew Oxygen Masks – Clogging of Ceramic Valves

TO see the details OF this Publication, please click OR copy the following: URL: <a href="http://ad.easa.europa.eu/ad/2019-08">http://ad.easa.europa.eu/ad/2019-08</a>

\* **AD** CF-2019-19 - C SERIES AIRCRAFT LP (CSALP): Fuel Distribution - Fuel Feed Tube Damage at Bonding Clamp Location Inside the Fuel Tank

TO see the details OF this Publication, please click OR copy the following: URL: <a href="http://ad.easa.europa.eu/ad/CF-2019-19">http://ad.easa.europa.eu/ad/CF-2019-19</a>