

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2011-0164R3** - AIRBUS HELICOPTERS: Rotors Flight Control – Tail Rotor Control Stop Screws – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2011-0164R3>

---

\* **SIB 2020-02R4** - Safety Information Bulletin: Coronavirus ‘SARS-CoV-2’ Infections – Operational Recommendations

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-02R4>

---

\* **SD SD-2020-01** - Safety Directives: Operational measures to prevent the spread of Coronavirus ‘SARS-CoV-2’ infection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/SD-2020-01>

---

\* **SD SD-2020-02** - Safety Directives: Operational measures to prevent the spread of Coronavirus ‘SARS-CoV-2’ infection

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/SD-2020-02>