The following Documents have been published or updated by EASA and may be of interest to you:

\* AD 2017-0134R2 - AIRBUS HELICOPTERS: Time Limits / Maintenance Checks – Main Gearbox Particle Detector / Oil Filter / Oil Cooler – Inspection Main Rotor Drive – Epicyclic Module – Replacement / Modification / Reduced Service Life Limit

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/2017-0134R2</u>

\* **SD** SD-2020-01 - Safety Directives: Operational measures to prevent the spread of Coronavirus `SARS-CoV-2` infection

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/SD-2020-01</u>

\* **SD** SD-2020-02 - Safety Directives: Operational measures to prevent the spread of Coronavirus `SARS-CoV-2` infection

TO see the details OF this Publication, please click OR copy the following: URL: <u>https://ad.easa.europa.eu/ad/SD-2020-02</u>