

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD BR-2020-04-01** - EMBRAER: Windows - Cockpit Side Windows - Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/BR-2020-04-01>