

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2020-0088** - AIRBUS: Electric and Electronic Common Installation – Ram Air Turbine Wiring Routing – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2020-0088>

* **AD 2020-0089** - AIRBUS: Nacelles / Pylons – Inboard Pylon Box at Rib 14 Fasteners – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2020-0089>

* **PAD 20-051R1** - AIRBUS: Nacelles / Pylons – Inboard Pylon Box Dog Head Fitting Holes – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/20-051R1>

* **PAD 20-063** - AIRBUS: Flight Controls – Flap Drive Struts and Lever Bearing Assemblies – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/20-063>

* **AD CF-2020-11** - BELL TEXTRON CANADA LTD (BTCL): Flight Controls – Incorrectly Staked Directional Control Bellcrank Bearing

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/CF-2020-11>