

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD G-014-01-92** - BAE SYSTEMS (OPERATIONS) LTD: [Cancelled] Placards and Markings - N2 limitations for anti-ice selection - To introduce a placard on the flight deck overhead panel and wiring to inhibit the airbrake auto-retract function.

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/G-014-01-92>

* **AD G-002-06-2000** - BAE SYSTEMS (OPERATIONS) LTD: SUPERSEDED BY EASA EMERGENCY AD 2009-0197-E

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/G-002-06-2000>

* **AD G-003-01-86** - BAE SYSTEMS (OPERATIONS) LTD: SUPERSEDED BY EASA AD 2013-0208

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/G-003-01-86>

* **AD G-003-04-94** - BAE SYSTEMS (OPERATIONS) LTD: SUPERSEDED BY EASA 2012-0036

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/G-003-04-94>

* **AD G-005-03-96** - BAE SYSTEMS (OPERATIONS) LTD: SUPERSEDED BY EASA AD 2017-0053

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/G-005-03-96>

* **AD G-005-02-2002** - BAE SYSTEMS (OPERATIONS) LTD: SUPERSEDED BY EASA AD 2017-0187

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/G-005-02-2002>

* **AD G-002-02-2003** - BAE SYSTEMS (OPERATIONS) LTD: SUPERSEDED BY EASA AD 2016-0211

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/G-002-02-2003>

* **AD G-019-09-81** - VIKING AIR LTD: SUPERSEDED BY EASA AD 2012-0159

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/G-019-09-81>

* **AD** G-004-03-99 - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: CANCELLED BY EASA AD 2012-0272-CN

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/G-004-03-99>

* **AD** G-002-01-2000 - ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG: SUPERSEDED BY EASA AD 2018-0202

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/G-002-01-2000>

* **AD** 2019-0314 - AIRBUS: SUPERSEDED BY EASA AD 2020-0093

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0314>

* **AD** 2020-0093 - AIRBUS: Hydraulic Power – Ground Service Manifold Manual Valve Attachment Screws – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-0093>

* **AD** CF-2020-12 - BOMBARDIER: Fire Protection – Fire Detection – Fire Detection and Extinguishing (FIREX) Control Unit Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/CF-2020-12>

* **PAD** 20-067 - AIRBUS HELICOPTERS: Equipment / Furnishings – Emergency Locator Transmitter – Inhibition / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/20-067>