

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2019-0255** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2020-0094

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2019-0255>

* **AD US-2020-05-26** - BOEING: Nacelles / Pylons - Strut Upper Spar Areas - Test

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/US-2020-05-26>

* **AD 2020-0094** - AIRBUS HELICOPTERS: Doors – Cargo Door Locking Mechanism – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2020-0094>

* **PAD 20-069** - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations
Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/20-069>

* **PAD 20-072** - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations
Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/20-072>

* **PAD 20-071** - DASSAULT AVIATION: Time Limits / Maintenance Checks – Airworthiness Limitations
Section Chapter 5-40 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/20-071>