

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2019-0195** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2020-0086

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2019-0195>

* **AD CF-2020-09** - BOMBARDIER: Landing Gear – General – Nose Landing Gear and Main Landing Gear Components Repaired by Bombardier Repair Engineering Orders Affected by Specific Airworthiness Limitation.

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/CF-2020-09>

* **AD US-2020-06-11** - MD HELICOPTERS INC (MDHI): Main Rotor Control - Main Rotor Blade Upper Control Collective / Longitudinal Link Assembly - Removal / Life Limit

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/US-2020-06-11>

* **AD 2020-0086** - AIRBUS HELICOPTERS: Tail Rotor – Hub Assembly – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/2020-0086>