

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2019-0001** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2020-0069

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2019-0001>

---

\* **AD 2020-0069** - AIRBUS HELICOPTERS: Doors – Sliding Door Opening Mechanism – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-0069>

---

\* **AD 2020-0070** - AIRBUS: Equipment / Furnishings – Emergency Locator Transmitter Protection – Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-0070>

---

\* **AD US-2020-06-02** - INTERNATIONAL AERO ENGINES LLC: Engine - Turbine Stator Intermediate Outer Rear Air Seal - Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/US-2020-06-02>

---