The following Documents have been published or updated by EASA and may be of interest to you:

* **PAD** 20-049 - AIRBUS: Electric and Electronic Common Installation — Ram Air Turbine Wiring Routing — Inspection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/20-049

* PAD 20-050 - AIRBUS: Nacelles / Pylons – Inboard Pylon Box at Rib 14 Fasteners – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/20-050

* PAD 20-051 - AIRBUS: Nacelles / Pylons – Inboard Pylon Box Dog Head Fitting Holes – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/20-051

* **PAD** 20-052 - AIRBUS: Oxygen – Oxygen Crew and Courier Distribution System Flexible Hoses – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/20-052

* SIB NM-20-02 - Safety Information Bulletin: Boeing 737-8 and 737-9 Aeroplanes - Fire Protection

TO see the details OF this Publication, please click OR copy the following: URL: https://ad.easa.europa.eu/ad/NM-20-02