The following Documents have been published or updated by EASA and may be of interest to you:

\* AD US-2020-04-11 - BOEING: Fuselage - Upper Skin Lap Splice - Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <a href="https://ad.easa.europa.eu/ad/US-2020-04-11">https://ad.easa.europa.eu/ad/US-2020-04-11</a>