

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** US-2020-08-12 - BOEING: Fuselage - Left and Right Side Lap Joints of the Fuselage Skin - Inspections / Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/US-2020-08-12>

* **AD** CF-2020-13 - PRATT & WHITNEY CANADA: Engine – Manual Calculation of Cycle Count for the Impeller and High Pressure Compressor Rotor

TO see the details OF this Publication, please click OR copy the following: URL:
<https://ad.easa.europa.eu/ad/CF-2020-13>