

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901

Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00061-2020 Date: 03/Mar/2020 Page 1 of 1

Type: /

EMB-145 Marks: N854AE Ata: 21 Aircraft Damages: Site: NOT AVAILABLE Injuries: X None Light: Departor: ENVOY Occurence Date: 20/Oct/2019 Number of Persons Aboard: Not Available Serious: 0 Fatal: 0	Aircraft:	Model:		Serial Number:
N854AE ENVOY 20/Oct/2019 Ata: 21 Time: Number of Persons Aboard: Not Available Aircraft Damages: Site: NOT AVAILABLE	EMB-145	EMB-135 H	KL	145743
Aircraft Damages: Site: NOT AVAILABLE		-		
Site: NOT AVAILABLE	Ata: 21	Time:		
NOT AVAILABLE	Aircraft Damages:			
Injuries: X None Light: 0 Serious: 0 Fatal: 0				
	Injuries: X None Lig	ght: 0	Serious: ⁰ Fata	ı: 0

Occurence Description:

Report of smoke and electric smell in the cockpit and cabin SMOKE IN COCKPIT ON DEPARTURE ELECTRIC SMELL IN C/P / CABIN. EMERGENCY DECLARED CHG EQ. FLT CONT. "TRANSFERRED TO NRWC 854-DFW-03157"WHILE PERFORMING GVI FOR SMOKE/ABNORMAL SMELL IN THE CABIN/COCKPIT FOUND LFWD ELECTRONIC COMPARTMENT FAN INOP.-C/A-RAR LFWD ELECTRONIC COMPARTMENT FAN IAW EMB 140 AMM 21-26-02. OPC CHECK GOOD.